


Figure 3 'Loss of SSI application ditches to runway construction'



Note: Ditch numbering follows that described by applicant's invertebrate survey (CD1.33a). Other information is from applicant's surface water drainage strategy (CD1.42a). There is some uncertainty over ditch numbering as applicant's invertebrate survey did not provide a map and locations have been inferred from the grid references provided, some of which were missing a digit.